

Henderson Township – Branch Road



Problem: A road side spring, groundwater and a lack of cross pipes were causing the road base and the road ditch to become saturated.

Solution: Four new cross pipes and two new through-the-bank pipes were installed. Four new turn outs were installed. The road base was built up 18”.

