

Beaver Township – Boddorf Road



Problem: Existing ditches were saturated with groundwater, causing road base cracking.

Solution: Installation of 540' of 10" underdrain and 300' of 6" underdrain to safely convey groundwater to outlet to a cross pipe. The road was patched where the surface was cracking.

