

Barnett Township – Songer Road

This is a Low Volume Road (LVR) Project.



Problem: A roadside spring saturated the ditch and road base. The water carried sediment and road material into an existing inlet box, causing the inlet box and pipe to plug and fail. The water also caused the road bank to erode.

Solution: The area surrounding the existing spring was stabilized with stone. A storm drain was installed to carry the spring water to the existing inlet box. The road banks were graded and seeded to stabilize them.

