

Warsaw Township – Crawford Road



Problem: The existing stream crossing was undersized and the road was acting as a ditch. Wet areas along the road were causing the ditches and road base to become saturated and form a large number of potholes.

Solution: A larger stream crossing was installed. A new underdrain and additional cross pipes were installed. The road was built up and turnouts were installed. The banks were graded to allow sheet flow and were stabilized with rip rap.

