

Young Township – Beyer Avenue Extension



Problem: Due to wetlands on both sides of the road and poor drainage, the road base was saturated. An existing cross pipe was plugged and crushed.

Solution: The existing cross pipe was replaced, two French Mattresses, 155 feet of underdrain, and 3 feet of road fill were installed to greatly improve drainage.

