

# Porter Township – Huber Road



**Problem:** Lack of adequate cross pipes and saturated road ditches cause the road to become soft.

**Solution:** Replaced an inadequate 12” cross pipe with an 18” cross pipe; replaced another existing 15” cross pipe with a 2’ squash pipe.

Installation of 3 additional 18” cross pipes.

Head and end walls were installed on each pipe and stone filters were installed at each outlet.

Installation of 619’ of 6” underdrain.

The road was built up 1’ to encourage sheet flow.

Disturbed areas were seeded and mulched.

