

Howe Township – Job Corps Road

Forest County



Problem: Water was running down steep roadside ditches for long distances, causing erosion. There were not enough crosspipes. The road surface was washboarding from the steepness of the hill and poor surface material.

Solution: Crosspipes and underdrains were added where needed to disperse runoff. 5,616 square yards of DSA were placed on the road surface to help stabilize it.

