

McCalmont Township – Native Road



Problem: The roadside springs were saturating the existing ditches and road base. Sediment was running into the nearby stream from the road surface. The road bank was eroding into the inlet of the existing cross pipe.

Solution: Underdrains and larger cross pipes were installed. Geotextile fabric was installed for road base support. The road base was built up to improve the road profile and encourage sheet flow. Gabion baskets were installed at the pipe inlets to support the banks.

