

Oliver Township – London Road



Problem: There was a wetland along the Township road, saturating the base and causing water to spring up in the middle of the road. This made the road base soft and created a large amount of sediment in the roadway. There was flowing water in the ditches, carrying sediment directly to the stream.

Solution: – An underdrain was installed to help keep the groundwater sediment free and to keep it from impacting the road base. A French mattress was installed. The road base was built up by placing geotextile fabric under shale to improve the road profile.

